Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	0019986	A. BUILDING: _____ B. WING _____	09/02/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCE ADULT HOME CARE LLC	283 VALLEY RIDGE DR SUN PRAIRIE, WI 53590

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 000	INITIAL COMMENTS On 09/02/2026, Surveyor conducted a standard survey at Advance Adult Home Care LLC, an AFH in Sun Prairie. One deficiency was identified. Census: 0	M 000		
M 332	88.05(4)(a) FIRE SAFETY-FIRE EXTINGUISHERS Fire extinguishers. Every adult family home shall be equipped with one or more fire extinguishers on each floor. Each required fire extinguisher shall have a minimum 2A, 10-B-C rating. All required fire extinguishers shall be mounted. A fire extinguisher is required at the head of each stairway and in or near the kitchen except that a single fire extinguisher located in close proximity to the kitchen and the head of a stairway may be used to meet the requirement for an extinguisher at each location. Each required fire extinguisher shall be maintained in readily usable condition and shall be inspected annually by the authorized dealer or the local fire department and have an attached tag showing the date of the last dealer or fire department inspection. This Rule is not met as evidenced by: Based on observation and interview, the provider did not ensure the home was equipped with 1 or more fire extinguishers mounted on each floor	M 332		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	0019986	A. BUILDING: _____ B. WING _____	09/02/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCE ADULT HOME CARE LLC	283 VALLEY RIDGE DR SUN PRAIRIE, WI 53590

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 332	Continued From page 1 and that the fire extinguishers were inspected annually by an authorized dealer or local fire department. The provider did not have fire extinguishers mounted on each floor and did not ensure fire extinguishers were inspected annually. Findings include: On 09/02/2026 at approximately 10:30 a.m., Surveyor toured the provider's home. Surveyor did not observe mounted fire extinguishers on the 1st floor, 2nd floor or basement. On 09/02/2026 at approximately 10:35 a.m., Surveyor interviewed Licensee A. Licensee A confirmed s/he did not have fire extinguishers mounted and showed Surveyor 2 fire extinguishers that were stored in a closet in the provider's kitchen. Licensee A stated the fire extinguishers had previously been mounted; however, had been removed since the home did not currently have residents. The fire extinguishers did not have a tag indicating when they had last been inspected and Licensee A was unsure when the fire extinguishers had last been inspected. Licensee A stated s/he would have the fire extinguishers inspected and mounted.	M 332		